

GM301-W, GM301-B 滑鼠

使用說明書

特徵:

相容 IBM PC 及筆記型電腦

支持 Windows 98/ME/2000/XP, VISTA, Win7, Mac10.0 等作業系統

支持隨插即用，不需要安裝驅動

安裝及產品功能

1. 開啟電腦。
2. 打開滑鼠包裝，取出滑鼠，將 USB 插入電腦上相對應的介面上，系統自動對滑鼠進行查找，相關驅動也是自動完成；移動滑鼠，光標或按鍵有反應時表示安裝完成。
3. USB 介面支持隨插即用，支持使用的時候熱拔插。
4. dpi 有 4 種速度可以做調整，依個人喜好選擇 800Dpi、1200Dpi、1600Dpi 或 2000Dpi。

單元 Unit	限用物質及其化學符號 Restricted substances and its chemical symbols					
	鉛Lead (Pb)	汞Mercury (Hg)	鎘Cadmium (Cd)	六價鉻 Hexavalent chromium (Cr ⁺⁶)	多溴聯苯 Polybrominated biphenyls (PBB)	多溴二苯醚 Polybrominated diphenyl ethers (PBDE)
電路板	○	○	○	○	○	○
外殼	○	○	○	○	○	○
線材	○	○	○	○	○	○
滾輪	○	○	○	○	○	○
按鍵	○	○	○	○	○	○

備考1. “超出0.1 wt %” 及 “超出0.01 wt %” 係指限用物質之百分比含量超出百分比含量基準值。

Note 1: “Exceeding 0.1 wt %” and “exceeding 0.01 wt %” indicate that the percentage content of the restricted substance exceeds the reference percentage value of presence condition.

備考2. “○” 係指該項限用物質之百分比含量未超出百分比含量基準值。

Note 2: “○” indicates that the percentage content of the restricted substance does not exceed the percentage of reference value of presence.

備考3. “—” 係指該項限用物質為排除項目。

Note 3: The “—” indicates that the restricted substance corresponds to the exemption.